

40-OK5110H

ASSEMBLY INSTRUCTION

CAUTION

1. INDOOR USE ONLY
2. REPLACE THE BULB AFTER THE BULB GETS COOL.

Assembly steps:

Step 1.pass the main wire(L)through the tube(B)

Step 2. Attach tube(B) to assembly (A).

Step 3. Mount the beads assembly(C) and shade(D)to the tube(B) and secure with loop (E).

Step 4.Hang bead string(A1),put the ring into the ring (A2).

Step 5. Mount ceiling fitting

Step5-1.Tighten loop(G)on the tube(H).

Step5-2.Loosen screw(K)and pass canopy (I) over the tube(H).

Step 5-3.Tighten loop(J) on the tube(H).

Step 5-4. pass the main wire(L)through the links of chain(F),loop(G),canopy(I), tube(H)and loop(J).

Step 5-5.Open and attach first link and last link of chain(F)to the loops(E) and(G),and use pliers to close the links of chain.

Step 5-6. Connect wire(L)to the power supply cord.

Step 5-7. raise the canopy(I)to ceiling and secure it by tightening the screw(K).

Step 5-8. Hang the Loop(J)on the hook on ceiling.

Step 6. turn in the bulb to the socket

After each step above, please check once more to make sure they were exactly assembled. Then have the power on.

If the external flexible cable or cord is damaged it shall be replaced exclusively by the manufacturer or service agent or similar qualified person to avoid hazard.